

ISSUE DATE
8/04/15

INITIAL REL. DATE
8/04/15



PRODUCT BULLETIN
SW-PB-104

REVISION LEVEL
B

SUBJECT: PZ-11 LINER WEAR PLATES

PAGE 1 OF 2

1.0 Description of Affected Products

PZ-11 Liner Wear Plates

2.0 Issue

SWOP (8477-4) Wear Plate cannot be used in Gardner Denver OEM Module

3.0 Fix

Follow action section below for proper ordering

4.0 Action

When servicing the (8477-8) SWOP Manufactured Gardner Denver Style Valve over Valve Module you must use the (8477-4) Liner Wear Plate.

When servicing the Original Gardner Denver Manufactured PZ-11 Valve over Valve Module you must use the (8477-53) Liner Wear Plate.

